

Photo documentation regarding the transport damage AVR (Automatic Voltage Regulator) Sterostab Y314AP80 , cod. 07725083, s/n 747575. Erwin Junker



Outside panels of the AVR are damaged and have to be replaced:

- Parete post. (back side)
- Fiancata (side panel)
- Coperchio (top closure)
- Porta SX (left door)
- Porta DX (right door)



The structure of the item is badly bent and has to be replaced:

- Traversa front (front crossbar)
- Telaio saldato (welded frame)
- Piede telaio (frame support)
- Fondo (bottom plate)

Vital electrical components are damaged and out of order

- Regolatore (autotransformer, including motor and carbon brushes)
- Scheda (electronic board)